Extractive Metallurgy Objective Questions and Answers Pdf

1. (Oxides of	which of the	e following	metals	decompose	by	heat	alone?
------	-----------	--------------	-------------	--------	-----------	----	------	--------

- a. Ag & Hg
- b. Cu & Sn
- c. Pb & Fe
- d. Zn & Cr

Ans: A

2. Copper, lead and zinc ores mostly occur in the form of

- a. Oxides
- b. Carbonates
- c. Sillicates
- d. Sulphides

Ans: D

3. Extraction of which of the following metals is the most expensive? a. Fe

- b. Au
- c. Zn
- d. Pb

Ans; B

4. Secondary metals are those

- a. Resulting from refining of scraps
- b. Resulting from reduction of their ores
- c. Which are having high level of impurities
- d. Which can be cold rolled

Ans: A

- 5. Percentage of copper in pure mineral is maximum (about 89%) in
 - a. Cuprite
 - b. Chalcopyrite
 - c. Chalcocite

d. Malachite

Ans: A

meritnotes.com