Heating and Welding Objective Questions and Answers Pdf

1 . In a resistance furnace the atmosphere is
a. oxidising
b. deoxidising
c. reducing
d. neutral
Ans: A
2. In induction heating is abnormally high.
a. phase angle
b. frequency
c. current
d. voltage
Ans: B
3. In an electric room heat convector the method of heating used is
a. arc heating
b. resistance heating
c. induction heating
d. dielectric heating
Ans: B
4. In an electric press mica is used
a. as an insulator
b. as a device for power factor improvement
c. for dielectric heating
d. for induction heating
Ans: A
5. Induction heating takes place in which of the following?

- a. insulating materials
- b. conducting materials which are magnetic
- c. conducting materials which are non magnetic
- d. conducting materials which may or may not be magnetic

Ans: D

meiithotes.com