## **Mechanical Measurements MCQ Questions and Answers Pdf**

The display of a digital numerical read out instrument is achieved by
a. light emitting diodes
b., light dependent resistors
c. phototube
d. ionization of gases
Ans C
2. An electrometer is used for the measurement of
a. voltages
b. currents
b. currents c. both a and b d. none of these Ans: C 3. Transistors have
d. none of these
Ans: C
3. Transistors have
a. low and positive temperature coefficient
b. low and negative temperature coefficient
c. high and negative temperature coefficient
d. zero temperature coefficient
Ans: C
4. The flow in open channel can be measured by
a. Pitot tube
b. Rotameter
c. Turbine meter
d. Venturimeter
Ans; A

5. Which of the following is not a source of power?
a. solar cell
b. photoelectric cell
c. photo voltaic cell
d, thermocouple
Ans: D
6. The material used in the construction of a thermistor is
a. nickel oxide
b. lion oxide
c. nickel
d. none of the above
Ans: A
d. none of the above  Ans: A  7. LVDT converts
a. linear displacement into electrical signal
b. pressure into electrical output
c. strain into electrical output
d. none of the above
Ans: A
8. Venturi tubes are generally made of
a. stainless steel
b. aluminium
c. cast iron
d. phosphor bronze
Ans: D
9. Photo conductive cells are used for

- a. detecting ships and aircrafts by radiation
- b. photometry and caloriemetry
- c. on and off circuits
- d. none of the above

Ans: A

- 10. A ring balance gauge is used to measure
- a. temperature
- b. differential pressure
- c. Gauge pressure
- d. vacuum pressure

Ans: B

meilinotes.com